Current part is item (10) on diagram. Available at www.oshkoshequipment.com

(1) SMR Code	(2) Federal Stock Number	(3) DESCRIPTION Reference Number & Mfr. Code	Usable On Code	(4) UNIT of meas	(5) Qty inc. in Unit	(6) 30-day DS maint allowance (a) 1-20	(b) 21-50	(c) 51-100	(7) 30-day GS maint allowance (a) 1-20	(b) 21-50	(c) 51-100	(8) 1-yr alw per 100 equip cnt-gcy	(9) Depot maint alw per 100 equip	(10) Illustration (a) Figure No.	(b) Item No.
		0802-CLUTCH AND CLUTCH CONTROLS-CONTINUED													
		NON-ILLUSTRATED-CONTINUED													
P-F	2520-734-6775	GASKET SET: POWER TRANSFER 7346775 (19207) CONSISTING OF:	A	EA	1	*	*	*	*	*	*	15	100		
		1-GASKET: INPUT SHAFT REAR BEARING COVER 7375291 (78500)												52	1
		1-GASKET: TRANSFER CASE COVER 7375246 (19207)												53	3
	2520-563-5523	1-GASKET: FRONT BEARING COVER 7375292 (19207)												53	17
	2520-563-5524	1-GASKET: OUTPUT SHAFT GEAR CASE 7375293 (19207)												53	23
		0803-TRANSFER CONTROLS													
P-F	5315-842-3154	PIN CLEVIS: LINK ROD MS35810-36 (96906)	A	EA	4	*	*	*	*	*	*	4	8	58	1
P-F	2520-740-9544	LINK ROD ASSEMBLY: TRANSFER CASE CONTROL 7409544 (19207)	A	EA	1	*	*	*	*	*	*	3	5	58	2
P-F	5315-839-5822	PIN,COTTER: CLEVIS PIN MS24665-353 (96906)	A	EA	4	*	*	*	*	*	*	6	10	58	3
P-F	2520-740-9542	LEVER,CONNECTING: LEFT HAND AND RIGHT HAND BELLCRANK MOTION 7409542 (19207)	A	EA	2	*	*	*	*	*	*	3	5	58	4
P-F	5310-982-4908	NUT,SELF-LOCKING: SUPPORT TO BRACKET MS21045-6 (96906)	A	EA	10	*	*	*	*	*	*	6	10	58	5
P-F		WASHER: 7974676 (19207)	A	EA	2	*	*	*	*	*	*	6	10	58	6
P-F	5305-269-2809	SCREW, CAP, HEXAGON: MS90726-66 (96906)	A	EA	2	*	*	*	*	*	*	6	10	58	7
P-F	2520-740-9546	LINK ROD ASSEMBLY: LEFT HAND CONTROL TO HAND LEVER 8332233 (19207)	A	EA	1	*	*	*	*	*	*	3	5	58	8
P-F	5310-809-8533	WASHER,PLAIN: CONTROL SHAFT MS27183-23 (96906)	A	EA	1	*	*	*	*	*	*	6	10	58	9
P2-F	2520-864-3016	LEVER ASSEMBLY: HAND SHIFT CONTROL 8332237 (19207)	A	EA	1	*	*	*	*	*	*	3	5	58	10
P-F	2530-312-0539	BUSHING: HAND LEVER 8332655 (19207)	A	EA	1	*	*	*	*	*	*	4	8	58	11
X1-F		LEVER,HAND 10871433 (19207)	A	EA	1							2		58	12

Current part is item (10) on diagram. Available at www.oshkoshequipment.com



Figure 58. Transfer controls.

Current part is item (10) on diagram. Available at www.oshkoshequip

Current part is item (10) on diagram. Available at www.oshkoshequip