Current part is item (7) on diagram. Available at www.oshkoshequipment.com



FIGURE 290. WIPER ASSEMBLY.

Current part is item (7) on diagram. Available at www.oshkoshequipment.com

Current part is item (7) on diagram. Available at www.oshkoshequipment.com

(1) ITEM NO.	(2) SMR CODE	(3) FSCM	(4) PART NUMBER	(5) DESCRIPTION AND USABLE ON CODE (UOC)	(6) QTY
				GROUP 2202 ACCESSORY ITEMS	
				FIG. 290 WIPER ASSEMBLY.	
1	MOOZZ	45152	0144915-11	HOSE,NONMETALLIC WIPER MOTOR INTAKE, EXHAUST MAKE FROM HOSE,P/N 246115	1
2	PAOZZ	45152	23344FX	INSERT,TUBE FITTING	8
3	PAOZZ	45152	926FX15	MOTOR,WINDSHIELD WI	2
4	PAOZZ	60703	FPDP321-1	MOTOR,WINDSHIELD WI	1
5	PFOZZ	79470	1469X4	ELBOW,PIPE TO TUBE	1
6	PFOZZ	45152	39281AX	SPACER,PLATE	4
7	PAOZZ	60703	F1650INS	VALVE,PLUG WIPER CONTROL	1
8	PAOZZ	39428	95491A140	WASHER,FLAT	2
9	PAOZZ	96906	MS27183-10	WASHER,FLAT	2
10	PAOZZ	45152	2886HX	SCREW,MACHINE HEAD,SLOTTED	2
11	PFOZZ	45152	1782HX1	SPACER,SLEEVE	1
12	PAOZZ	70412	10202	ARM,WINDSHIELD WIPE	2
13	PAOZZ	70412	18794	BLADE,WINDSHIELD WI	2
14	PFOZZ	16662	AC302	ADAPTER,STRAIGHT,PI	12
15	MOOZZ	45152	4434746-86	HOSE,NONMETALLIC LH WIPER VALVE TO LH WIPER MOTOR (PARK), RH WIPER VALVE TO RHWIPER MOTOR, MAKE FROM HOSE,P/N 23319FX	1
16	MOOZZ	45152	4434746-120	HOSE,NONMETALLIC CAB AIR MANIFOLD TO LH WIPER VALVE AND TO RH WIPER, RH WIPER,RH WIPER VALVE MAKE FROM HOSE,P/N 23319FX	1
17	MOOZZ	45152	4434746-112	HOSE,NONMETALLIC LH WIPER VALVE TO LH WIPER MOTOR, RH WIPER VALVE TO RH WIPER MOTOR (RUN), MAKE FROM HOSE,P/N 23319FX	1
				END OF FIGURE	

Current part is item (7) on diagram. Available at www.oshkoshequipment.com