

(1) (2)
SMR Federal
Code Stock
Number

(3)
DESCRIPTION

TM9-2320-211-34P

(4) (5) (6)

(7)

(8) (9) (10)

Current part is item (26) on diagram. Available at www.oshkoshequipment.com

UNIT of meas in Unit
of inc. allowance
of allowance
alw maint
per alw
100 per (a) (b)
equip100 Figure Item
cnt- equipNo. No.
(a) (b) (c) (a) (b) (c)
1-20 21-5(51-10(1-20 21-5(51-10(gcy


Reference Number & Mfr. Code

Usable On Code

1802-FENDERS,RUNNING BOARDS,
WINDSHIELDS-CONTINUED

P-F	2510-737-33	FRAME ASSEMBLY,WINDSHIELD: OUTER 7373331 (19207)	A	EA	1	*	*	*	*	*	*	6	10	137	14
P-F	5305-350-12	SCREW,MACHINE: ADJUSTING ARM 7374809 (19207)	A	EA	8	*	*	*	*	*	*	6	10	137	15
P-F	2510-693-06	ARM ASSEMBLY,ADJUSTING: 7373327 (19207)	A	EA	4	*	*	*	*	*	*	6	10	137	16
P-F	2510-693-06	RETAINER,WINDSHIELD: 7373324 (19207)	A	EA	2	*	*	*	*	*	*	6	10	137	17
P-F	5305-051-64	SCREW,MACHINE: WINDSHIELD RETAINER MS24649-34 (96906)	A	EA	V									137	18
P-F	9320-599-64	RUBBER SEAL: WINDSHIELD OUTER FRAME TO DOOR GLASS	A	FT	2	*	*	*	*	*	*	8	20	137	19
P-F	9320-641-11	RUBBER,SPECIAL,SHAPED SECTION: WINDSHIELD OUTER FRAME TO DOOR GLASS LOWER 8724456 (19207)	A	EA	2	*	*	*	*	*	*	8	20	137	20
P-F	2510-693-06	RETAINER,WINDSHIELD: 7373336 (19207)	A	EA	2	*	*	*	*	*	*	6	10	137	21
P-F	9320-737-33	RUBBER,SPECIAL SHAPED SECTION: WINDSHIELD TO COWL 7373337 (19207)	A	EA	1	*	*	*	*	*	*	8	20	137	22
P-F	5305-638-09	THUMBSCREW: WINDSHIELD ADJUSTING ARM 7529322 (19207)	A	EA	4	*	*	*	*	*	*	6	10	137	23
P-F	5306-059-40	BOLT,ASSEMBLED WASHER: 594001 (21450)	A	EA	2	*	*	*	*	*	*	6	10	137	24
P-F	2510-737-33	PLATE,CATCH: WINDSHIELD INNER FRAME LOCKING HANDLE 7373326 (19207)	A	EA	2	*	*	*	*	*	*	6	10	137	25
P-F	5340-696-02	LEAF,BUTT HINGE: WINDSHIELD GLASS FRAME TO OUTER FRAME M3004 (70230)	A	EA	2	*	*	*	*	*	*	4	8	137	26
P-F	5305-350-12	SCREW,MACHINE: ADJUSTING ARM 7374809 (19207)	A	EA	8									137	27
NON-ILLUSTRATED															
P-F	2510-104-45	PANEL: FENDER,RIGHT SIDE,COMPLETE 10864585 (19207)	A	EA	1	*	*	*	*	*	*	4	10		
P-F	2510-107-42	PLATE,ASSEMBLY,LOUVER: 11608902 (19207)	A	EA	1	*	*	*	*	*	*	4	10		
P-F	2510-420-50	PANEL: FENDER SIDE 10931943 (19207)	A	EA	1	*	*	*	*	*	*	4	10		

Current part is item (26) on diagram. Available at www.oshkoshequipment.com



AT 47277

Figure 137. Windshield assembly.