



FIGURE 48. BATTERY AND RELATED PARTS.

TA 237935

SECTION II				TM 9-2320-283-34P	
(1)	(2)	(3)	(4)	(5)	(6)
ITEM	SMR		PART		
NO	CODE	CAGEC	NUMBER	DESCRIPTION AND USABLE ON CODES (UOC)	QTY
GROUP: 0613 HULL OR CHASSIS WIRING HARNESS					
FIGURE 51. WIRING HARNESSES (CAB TO FRAME, ENGINE TO FRAME, BLACKOUT MARKER LAMP, BLACKO1JT HEADLAMP).					
1	PBOZZ	34623	5981891	LEADSIGNITION, ENGIN CAB TO FRAME	1
2	PAOZZ	96906	MS45904-72	WASHER,LOCK.....	1
3	PAOZZ	24617	128226	SCREW,TAPPINGTHREA.....	1
4	PAOZZ	24617	q413534	NUT,SELF-LOCKING HE	1
5	PAOZZ	24617	178551	WASHERLOCK.....	2
6	PAOZZ	Q6906	MS90726-60	SCREW,CAP,HEXAGCNC.....	1
7	PAOZZ	96906	MS90728-64	SCREW CAP,HEXAG(N).....	1
8	PBOZZ	34623	MA73-20011	LEAD,ELECTRICAL ENGINE TO FRAME	1
9	PAOZZ	34623	5571127	LEAD,ELECTRICAL BLACK-OUT MARKER.....	2
10	PAOZZ	34623	MB73-20006	LAMP.....	
				CABLE ASSEMBLY,SPEC BLACK-OUT.....	1
				HEADLAMP.....	
11	PAOZZ	34623	5962558	LEAD,ELECTRICAL.....	1

END OF FIGURE

51-1

