


(1) SMR Code	(2) Federal Stock Number	(3) Description Reference number & mfg. code	(4) Unit Of Meas.	(5) Qty Inc In Unit	(6) 15-day organizational Maintenance alw				(7) Illustration	
					(a) 1-5	(b) 6-20	(c) 21-50	(d) 51-100	(a) Figure No.	(b) Item No.
					Usable on code					
		0607—INSTRUMENT PANEL—Continued								
P-O	5307-752-6594	STUD, EXTENSION, MOUNTING: instrument cluster circuit breaker to gage wiring harness 7526594 (19207)	EA	1	*	*	*	*	24	18
P-O	5310-752-6591	PUSH ON NUT: instrument cluster, mounting plate stud 7526591 (19207) "Non-Illustrated"	EA	4	*	*	*	*	24	19
P-O	2590-752-6599	WIRING HARNESS: instrument panel light 7526599 (19207)	EA	1	*	*	*	*		
		0608—MISCELLANEOUS ITEMS								
P-O	6240-419-3185	LAMP, INCANDESCENT: directional control handle MS25231-1878 (96906)	EA	1	*	*	*	*	25	6
P-O	2590-050-8821	KIT, SOLID STATE TURN SIGNAL: with hazard warning 11630590 (19207) Consisting of:	EA	1	*	*	*	*		
P-O	5935-399-6676	TERMINAL 8338564 (19207)	EA	6	*	*	*	*	25	1
P-O	5970-833-8562	SLEEVE 8338562 (19207)	EA	6	*	*	*	*	25	2
P-O	5935-833-8561	SHELL 8338561 (19207)	EA	6	*	*	*	*	25	3
XI		CABLE 11630528 (19207)		1					25	4
P-O	6220-422-2023	CONTROL 11613632 (19207)	EA	1	*	*	*	*	25	5
P-O	6220-181-2388	LENS ASSY MIL-C-62069/3AT (19207)	EA	1	*	*	*	*	25	7
P-O	5945-789-3706	FLASHER, SOLID STATE 11613631 (19207)	EA	1	*	*	*	*	25	8
P-O	5306-042-3545	SCREW: 423545 (24617)	EA	2	*	*	*	*	25	9
P-O	5310-080-9786	WASHER MS45904-60 (96906)	EA	1	*	*	*	*	25	10
		"Non-Illustrated"								
P-O	2590-307-8856	SWITCH, LIGHT: assembly MS5113-1 (96906)	EA	1	*	*	*	*		
P-O	2920-776-0409	SWITCH, IGNITION: assembly 7760409 (19207)	EA	1	*	*	*	*		



AT 40622