



Current part is item (3) on diagram. Available at www.oshkoshequipment.com

(1) SMR Code	(2) Federal Stock Number	(3) Description	(4) Unit of Meas.	(5) Qty	(6) 15-day Maintenance In Unit	(7) Organizational alw Illustration	(a) Figure No.	(b) Item No.
Reference number & mfg. code			Usable on code		(a) (b) (c) (d)			
4701-INSTRUMENTS (SPEED AND DISTANCE) -CONTINUED)								
PAOZZ	5310-950-0039	NUT,SELF-LOCKING:SPEEDOMETER SHAFT CLAMP MS21044N6 (96906)	A	EA	3	* * * *	207	17
PAOZZ	5340-282-7509	CLAMP,LOOP:SPEEDOMETER SHAFT MS21333-62 (96906)	A	EA	4	* * * *	207	18
PAOZZ	5305-269-2801	SCREW,CAP,HEXAGON HEAD:3/8-24UNF-2A X 3/4 IN. SPEEDOMETER SHAFT CLAMP MS90726-58 (96906)	A	EA	2	* * * *	207	19
PAOZZ	5305-068-0502	SCREW,CAP,HEXAGON HEAD:1/4-20UNC-2A X 3/4 IN. SHAFT CLAMP MS90725-6 (96906)	A	EA	1	* * * *	207	20
PAOZZ	5310-809-4058	WASHER,FLAT:.281 ID. SPEEDOMETER CABLE CLAMP MS27183-10 (96906)	A	EA	1	* * * *	207	21
PAOZZ	5310-959-7600	NUT,SELF-LOCKING:SPEEDOMETER AND TACHOMETER SHAFT CLAMP MS51922-5 (96906)	A	EA	2	* * * *	207	22
PAOZZ	5330-199-5882	GASKET:GEAR COVER TO TACHOMETER DRIVE ADAPTER MS35769-26 (96906)	AB	EA	1	* * * *	208	1
PAOZZ	6620-084-7621	ADAPTER,TACHOMETER: TAKE-OFF 10912497 (19207)	AB	EA	1	* * * *	208	2
PAOZZ	2815-995-1811	ADAPTER ASSEMBLY:TACHOMETER DRIVE,RIGHT ANGLE 11610078 (19207)	AB	EA	1	* * * *	208	3



TA 009329



Current part is item (3) on diagram. Available at www.oshkoshequip.com

Figure 208. Tachometer drive and takeoff adapters—multifuel.

Current part is item (3) on diagram. Available at www.oshkoshequip.com