


TA212416

FIGURE 290. WIPER ASSEMBLY.

Current part is item (7) on diagram. Available at www.oshkoshequipment.com

SECTION II				TM9-2320-270-34P	
(1)	(2)	(3)	(4)	(5)	(6)
ITEM NO.	SMR CODE	FSCM	PART NUMBER	DESCRIPTION AND USABLE ON CODE (UOC)	QTY
GROUP 2202 ACCESSORY ITEMS					
FIG. 290 WIPER ASSEMBLY.					
1	MOZZ	45152	0144915-11	HOSE, NONMETALLIC WIPER MOTOR INTAKE, EXHAUST MAKE FROM HOSE, P/N 246115	1
2	PAZZ	45152	23344FX	INSERT, TUBE FITTING	8
3	PAZZ	45152	926FX15	MOTOR, WINDSHIELD WI	2
4	PAZZ	60703	FPDP321-1	MOTOR, WINDSHIELD WI	1
5	PFOZZ	79470	1469X4	ELBOW, PIPE TO TUBE	1
6	PFOZZ	45152	39281AX	SPACER, PLATE	4
7	PAZZ	60703	F1650INS	VALVE, PLUG WIPER CONTROL	1
8	PAZZ	39428	95491A140	WASHER, FLAT	2
9	PAZZ	96906	MS27183-10	WASHER, FLAT	2
10	PAZZ	45152	2886HX	SCREW, MACHINE HEAD, SLOTTED	2
11	PFOZZ	45152	1782HX1	SPACER, SLEEVE	1
12	PAZZ	70412	10202	ARM, WINDSHIELD WIPE	2
13	PAZZ	70412	18794	BLADE, WINDSHIELD WI	2
14	PFOZZ	16662	AC302	ADAPTER, STRAIGHT, PI	12
15	MOZZ	45152	4434746-86	HOSE, NONMETALLIC LH WIPER VALVE TO LH WIPER MOTOR (PARK), RH WIPER VALVE TO RHWIPER MOTOR, MAKE FROM HOSE, P/N 23319FX	1
16	MOZZ	45152	4434746-120	HOSE, NONMETALLIC CAB AIR MANIFOLD TO LH WIPER VALVE AND TO RH WIPER, RH WIPER, RH WIPER VALVE MAKE FROM HOSE, P/N 23319FX	1
17	MOZZ	45152	4434746-112	HOSE, NONMETALLIC LH WIPER VALVE TO LH WIPER MOTOR, RH WIPER VALVE TO RH WIPER MOTOR (RUN), MAKE FROM HOSE, P/N 23319FX	1

END OF FIGURE



Current part is item (7) on diagram. Available at www.oshkoshequipment.com